

FLORIDA DEPARTMENT OF Environmental Protection

Bob Martinez Center 2600 Blair Stone Road Tallahassee, Florida 32399-2400 Rick Scott Governor

Carlos Lopez-Cantera Lt. Governor

> Noah Valenstein Secretary

Phase I Municipal Separate Storm Sewer System (MS4) NPDES Stormwater Audit Report

I. BACKGROUND INFORMATION

MS4 Permit Name:	Palm Beach County
Permittee:	Village of Palm Springs
Permit Number:	FLS000018 (Cycle 4)
Annual Report Year:	Year 1
Reporting Period:	10/01/2016 - 09/30/2017
Audit Date/Time:	June 7, 2018 7:45 am – 12:00 pm

Inspector(s):

Name	Title	Phone/ Email
Michelle Bull	Environmental Consultant	850-245-7561
		Michelle.Bull@dep.state.fl.us

Permittee Representative(s):

Name	Title	Phone
Angie Thul	Stormwater Program	561-434-5122
	Coordinator	athul@vpsfl.org
Chad Girard	Assistant Public Service	561-641-3440
	Director	cgirard@vpsfl.org
Alan Wertepny	Mock-Roos	561-683-3113 x 231
		alan.wertepny@mockroos.com

II. GENERAL COMMENTS

Angie was very knowledgeable about the Village's stormwater system and activities. Her recordkeeping is very thorough, which helped the audit go very smoothly.

III. SITE VISITS

□ Satisfactory

⊠ Unsatisfactory

□ Not Applicable

Site Type: Construction Site

Site Name and Location: Chase Bank, 2601 10th Avenue North Applicable Permit Provision(s): Part III.A.9.b

Observations: Inspected Chase Bank construction site. Reviewed ERP 10-2 Self Certification and onsite SWPPP. Site was less than one acre. Gravel entrance was well maintained and there was no offsite sediment. Existing and new catch basins were protected by filter fabric. Perimeter controls were in place

Village of Palm Springs MS4 Year 1 Audit Report Page 2

and in good condition. The site was very clean and organized. No sediment or trash was seen leaving the site. Angie inspected the site weekly, and did not note any violations.

Site Type: Maintenance Shop

Site Name and Location: Village of Palm Springs Water Plant

Applicable Permit Provision(s): Part III.A.3

Observations: Fleet maintenance and storage onsite. Parking lot was clean, no catch basins noted. Site drained to a low-lying area at back of property. Noted some erosion and trash in low area. Used oil and filters were stored under cover, but did not have secondary containment. Paint was stored indoors and in secondary containment. Equipment was stored under cover.

Image 1: Used Oil Storage

Image 2: Low Lying Area



Required Improvements:

Provide secondary containment for used oil storage. Within 30 days of the audit report, provide images of waste storage in secondary containment.

Remove trash/debris from drainage/low area, and install erosion controls to prevent erosion of the parking lot and sediments. **Within 30 days of the audit**, provide images of drainage area.

IV. SWMP IMPLEMENTATION REVIEW

Monitoring Program

□ Satisfactory

 \boxtimes Unsatisfactory

 \Box Not Applicable

Assessment Plan: Not approved.

Required Improvement: Within 30 days of the audit report, submit a plan that contains a revised map with, City boundaries and joint monitoring location; and a description of how water quality/loading data will be used to identify portions of the MS4 which can be targeted for loading reduction /corrective action with additional pollutant reduction measures.

Fiscal Analysis

Comments: Expenditures matched budget. Next year has increased.

TMDL Prioritization

Village of Palm Springs MS4 Year 1 Audit Report Page 3

 \boxtimes Satisfactory \square Unsatisfactory \square Not Applicable

TMDL Prioritization Plan: Did not discharge to a TMDL WBID at the time of permit issuance.

Part III.A.1: Structural Controls and Stormwater Collection Systems Operation

\mathbf{X}	Satisfactory	□ Unsatisfactory	Not Applicable
~ ~	Datisfactory		1 of Applicable

Major Outfall Inventory: Inventory changed from 23 to 14. The Village was previously counting discharges to private lakes as major outfalls, which are not discharges to waters of the state. Updated inventory to only report major outfalls to Lake Worth Drainage district. Some of those outfalls to private lakes are submerged.

Structural Control Inventory:

The Village performs most of its own maintenance. Outsource landscaping. Planning to contract out ditch maintenance. Recently started using Munis software to track work orders. Reviewed invoice for Vincent and Sons Landscaping, which includes litter control before mowing. Also maintain Congress Avenue ROW (owned by FDOT).

Structural Control Inspections:

Dry Retention: reviewed SOP, inspected wet and dry seasons. Reviewed inspection reports, and followup Munis work order to remove sediment at inlet pipe.

Wet Detention: Reporting private lakes (stormwater Systems) surrounded by private homes. Only inspecting MS4 outfalls into system every other year, due to boat access required. In future, do not report wet detention, as they are private systems not maintained by the Village.

Treatment Swales: reviewed SOP and inspection tracking. Tracking by road, and inspects each section. **Exfiltration Trenches**: Reviewed SOP, 11 structures. Reviewed inspection checklists. No maintenance required in reporting period.

Catch basins: Scheduled to be inspected in dry season. Angie Thul inspects then schedules vac truck with Utility Department in Munis software. Timing of vac response may depend on type of issue. Sediment may take a couple weeks, while emergencies like illegal dumping handled within day. Reviewed inspection tracking list; work orders in Munis system which include completed date; and an invoice for contractor to replace collapsed pipe.

Pipes: done with catch basin inspections. Reviewed Culvert inspection tracking.

Major outfalls -scheduled for wet season. Reviewed tracking sheet and inspection checklists done in May/June. The Village will continue to inspect non-MS4 outfalls.

Part III.A.2: Areas of New Development and Significant Redevelopment

⊠ Satisfactory

□ Unsatisfactory

□ Not Applicable

New/Redevelopment Projects: 9 reviewed and 5 approved by Building Planning and Zoning

Part III.A.3: Roadways

⊠ Satisfactory

□ Unsatisfactory

 \Box Not Applicable

Litter Control: contracted

Pick Up Events: Keep PBC beautiful

Street Sweeping: No curb/gutter. Congress Ave is owned/swept by FDOT.

Road Maintenance Yards: Reviewed inspection checklist. No vehicle wash. Above ground fueling.

Maintenance Shop - inspected. See Part III.

Equipment Yard - not inspected during audit.

Part II	I.A.4: Flood Control Pro	ojects	
🖾 Sat	tisfactory	□ Unsatisfactory	□ Not Applicable
Not revi	ewed during audit.		
	I.A.5: Municipal Waste vered by an NPDES Sto	Treatment, Storage, and Dispo ormwater Permit	osal Facilities
🗵 Sat	tisfactory	□ Unsatisfactory	□ Not Applicable
Waste S	Storage Facilities: No facil	ity.	
Part II	I.A.6: Pesticides, Herbic	cides, and Fertilizer Applicatio	n
🛛 Sat	tisfactory	□ Unsatisfactory	□ Not Applicable
GIBMP fertilizer Reviewe Fertilize Public E	rs at ball fields. ed list of parks and village p er Ordinance: Not in nutrie Education: Quarterly news	staff have commercial fertilizer app property on landscaping bid. ent impaired WBID letter	olicator licenses. May apply
	I.A.7.a: Illicit Discharge tions, Ordinances, and H	s and Improper Disposal — Enforcement Measures	
🛛 Sat	tisfactory	□ Unsatisfactory	□ Not Applicable
Not revi	ewed during audit.		
		s and Improper Disposal — it Discharges and/or Improper	Disposal
🗵 Sat	tisfactory	□ Unsatisfactory	□ Not Applicable
Illicit Di basin ins Reactiv	ischarge inspection report re spection. Staff also look for	ctural control inspections. Have "II eviewed: Dumpsters discharging int dumping during canal inspections. ted. Discussed educating the public	to storm drain, noted during catch
	I.A.7.d: Illicit Discharge revention and Response	es and Improper Disposal —	
🗵 Sat	tisfactory	□ Unsatisfactory	□ Not Applicable
no curb,	partment: Recommend ask low speed limit, unlikely to	ing Fire Rescue how they respond have car accidents. Congress Ave Recommend training staff that hand	is FDOT.

maintenance yard staff that perform oil changes, fuel vehicles, patch roads, etc. I suggest contacting Mock-Roos for training.

Village of Palm Springs MS Year 1 Audit Report Page 5	54			
Part III.A.7.e: Illicit Dis Public Reporting	charges and Improper Disposa	1—		
⊠ Satisfactory	□ Unsatisfactory	□ Not Applicable		
Website/Phone: Discussed Public Education: website	d public education for residents to re	port illicit discharges.		
	charges and Improper Disposa hold Hazardous Waste Control	I—		
⊠ Satisfactory	□ Unsatisfactory	□ Not Applicable		
homes quarterly. Discussed		sletter, which is distributed to 12,000 o do education for properly disposing of		
Part III.A.7.g: Illicit Dis Limitation of Sanitary S	scharges and Improper Disposa Sewer Seepage	1—		
□ Satisfactory	□ Unsatisfactory	⊠ Not Applicable		
Not discussed during audit.				
	al and High-Risk Runoff — ies and Procedures for Inspection	ons		
⊠ Satisfactory	□ Unsatisfactory	□ Not Applicable		
High risk facilities: No fac	cilities.			
Part III.A.8.b: Industria Monitoring for High Ri	al and High-Risk Runoff — sk Industries			
⊠ Satisfactory	□ Unsatisfactory	□ Not Applicable		
Monitoring: See above.				
Part III.A.9.a: Construction Site Runoff — Site Planning and Non-Structural and Structural Best Management Practices				
Satisfactory	□ Unsatisfactory	□ Not Applicable		
Site Plan Review: 8 reviewed, 4 approved. The Village may contract erosion and sediment control.				
Part III.A.9.b: Construct Inspection and Enforce				
⊠ Satisfactory	□ Unsatisfactory	□ Not Applicable		
CGPs.	pections. Reviewed inspection check	lists and ERP coverage or self-cert and nings for silt fences and truck pads (no		

Part III.A.9.c: Construction Site Runoff — Site Operator Training

⊠ Satisfactory

□ Unsatisfactory

□ Not Applicable

Inspector E&SC Training: Angle has DEP erosion and sediment control certification, and attended annual refresher training with Steering Committee, did not report.

Site Plan Reviewer Training: Reported 0. Discussed building staff, and contracted site plan review. Contracted engineers include sediment control in their review of the Utility/Civil plans.

Site Operator Training: N/A; no permittee construction.