## -Town of Jupiter Inlet Colony-

Site address: <u>12 Ocean Drive</u>	_	
Date of inspection: <u>November 7<sup>th</sup>, 2018</u>		
Contractor performing the work:		
Is it raining during the inspection?	YES	NO <u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup>, 2018</u>		
Is this inspection Pre, During, or Post Construction:Du	iring Cons	struction
INSPECTION:		
Does this site include the appropriate erosion control?	YES <u>X</u>	_ NO
If yes, what measures have been implemented? Silt Fence		
Are these measures properly installed or maintained?	YES	NO <u>_X</u>
Silt fence has been repaired. There was still a notable amount of gravel to areas of loose soil/sand would help control this issue.	sand in va	alley gutter. Applying
Debris or sediment accumulation in inlet/catch basin/grate?	YES	XNO
If yes, does evidence indicate this is a recent issue?	YES	NOX
Is there evidence of sediment/sand/debris tracked into roadway?	YES <u>X</u>	NO
If YES, report to supervisor for further investigation or schedule for	or mainter	nance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES	NOX
Does associated outfall display evidence sediment passage?	YES	NOX

If YES, complete Illicit Discharge Form and submit to supervisor for proper response.

# -Town of Jupiter Inlet Colony-

Site address: <u>14 Ocean Drive</u>	_	
Date of inspection: <u>November 7<sup>th</sup></u> , 2018		
Contractor performing the work:		
Is it raining during the inspection?	YES	_NO <u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup></u> , 2018		
Is this inspection Pre, During, or Post Construction:	uring Const	truction
INSPECTION:		
Does this site include the appropriate erosion control?	YES	_NO <u>X</u>
If yes, what measures have been implemented?		
Are these measures properly installed or maintained?	YES	NO <u>X</u>
Heavy sediment tracking into valley gutter. Construction is mulch/gravel has been installed in landscaping to control sedime the landscaping and gravel for the large paver driveway would help the quality of construction after completion.	nt washing	. Applying mulch in
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule for maintenance.		
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES	NOX
Does associated outfall display evidence sediment passage?	YES	NO <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for proper	response
Type of Enforcement Action Taken: Will advise Chief John Pruit		
Date to Verify Implementation: Dec. Monthly Inspection		

## -Town of Jupiter Inlet Colony-

Site address: <u>32 Ocean Drive (Blue House)</u>		_		
Date of inspection: <u>November 7<sup>th</sup></u> , 2018				
Contractor performing the work:		_		
Is it raining during the inspection?	YES_	N	10	<u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup>, 2018</u>	_			
Is this inspection Pre, During, or Post Construction:Du	ring Co	nstruc	ction_	
INSPECTION:				
Does this site include the appropriate erosion control?	YES _	<u>X</u>	NO_	
If yes, what measures have been implemented? <u>_Silt Fence</u> <u>Construction is approaching completion.</u>	es were	used	when	needed.
Are these measures properly installed or maintained?	YES_	<u>X</u>	NO_	
Construction is approaching completion. The site was very clean of	verall.			
Debris or sediment accumulation in inlet/catch basin/grate?	YES_		NO _	<u>X</u>
If yes, does evidence indicate this is a recent issue?	YES_		NO _	<u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES_		NO _	<u>X</u>
If YES, report to supervisor for further investigation or schedule for	or maint	enanc	ce.	
OUTFALL CONDITION:				
Any indications of erosion on bank near associated outfall?	YES_		NO_	<u>X</u>

Does associated outfall display evidence sediment passage? YES \_\_\_\_\_ NO \_\_X\_\_\_

If YES, complete Illicit Discharge Form and submit to supervisor for proper respons

Type of Enforcement Action Taken: Will notify Chief John

Date to Verify Implementation: Dec. Monthly Inspection

# -Town of Jupiter Inlet Colony-

Site address: 59 Colony Road		
Date of inspection: <u>November 7<sup>th</sup>, 2018</u>		
Contractor performing the work:		
Is it raining during the inspection?	YES	NO <u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup>, 2018</u>		
Is this inspection Pre, During, or Post Construction:	uring Con	struction
INSPECTION:		
Does this site include the appropriate erosion control?	YES	NO <u>X</u>
If yes, what measures have been implemented? Silt fem		be implemented, sand aded the valley gutter.
Are these measures properly installed or maintained?	YES	NOX
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NOX
Is there evidence of sediment/sand/debris tracked into roadway?	YES	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule f	for mainte	nance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES	NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES	NO <u></u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prope	r respons

Type of Enforcement Action Taken: Will report to Police Chief John Pruitt.

Date to Verify Implementation: Dec. Monthly Inspection

-Town of Jupiter Inlet Colony-

Site address: <u>82 Lighthouse Drive</u>	_	
Date of inspection: <u>November 7<sup>th</sup></u> , 2018		
Contractor performing the work:		
Is it raining during the inspection?	YES	NO <u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup>, 2018</u>	_	
Is this inspection Pre, During, or Post Construction:Du	ring Constr	ruction
INSPECTION:		
Does this site include the appropriate erosion control?	YES	NO <u>X</u>
If yes, what measures have been implemented?		
Are these measures properly installed or maintained?	YES	NOX
No signs of tracking. A silt fence implementation would be ideal.		
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES	_NOX
If YES, report to supervisor for further investigation or schedule for	or maintena	ince.
OUTFALL CONDITION:		

Any indications of erosion on bank near associated outfall?	YES	_NO_	<u>X</u>
Does associated outfall display evidence sediment passage?	YES	_NO_	<u>X</u>

If YES, complete Illicit Discharge Form and submit to supervisor for proper respons

Type of Enforcement Action Taken: <u>None</u>

Date to Verify Implementation:

## -Town of Jupiter Inlet Colony-

Site address: <u>100 Lighthouse Drive</u> (Gym Construction)		
Date of inspection: <u>November 7<sup>th</sup>, 2018</u>		
Contractor performing the work:		
Is it raining during the inspection?	YES	NO <u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup>, 2018</u>	_	
Is this inspection Pre, During, or Post Construction:Du	tring Constr	ruction
INSPECTION:		
Does this site include the appropriate erosion control?	YES	NO <u>X</u>
If yes, what measures have been implemented?		
Are these measures properly installed or maintained?	YES	NO <u>X</u>
Plywood is laid to prevent tracking. A silt fence would be ideal.		
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	_NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule for	or maintena	nce.

## **OUTFALL CONDITION:**

Any indications of erosion on bank near associated outfall?	YES	_NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES	_NO _ <u>X</u>

If YES, complete Illicit Discharge Form and submit to supervisor for proper respons

-Town of Jupiter Inlet Colony-

Site address: 115 Lighthouse Drive	_	
Date of inspection: November 7 <sup>th</sup> , 2018		
Contractor performing the work:		
Is it raining during the inspection?	YES	NO <u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup></u> , 2018		
Is this inspection Pre, During, or Post Construction:	uring Con	struction
INSPECTION:		
Does this site include the appropriate erosion control?	YES	NOX
If yes, what measures have been implemented?		
Are these measures properly installed or maintained?	YES	NO <u>X</u>
Sediment is being tracked into the road. Regular street sweeping	and clean	ing should suffice.
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES	<u>X</u> NO
If YES, report to supervisor for further investigation or schedule f	or mainte	enance.
OUTEALL CONDITION.		

### **OUTFALL CONDITION:**

Any indications of erosion on bank near associated outfall?	YES	NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES	NOX

If YES, complete Illicit Discharge Form and submit to supervisor for proper respons

-Town of Jupiter Inlet Colony-

Site address: <u>126 Lighthouse Drive</u>	_
Date of inspection: November 7 <sup>th</sup> , 2018	
Contractor performing the work:	
Is it raining during the inspection?	YES NO <u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup></u> , 2018	_
Is this inspection Pre, During, or Post Construction:	uring Construction
INSPECTION:	
Does this site include the appropriate erosion control?	YES NOX
If yes, what measures have been implemented?	
Are these measures properly installed or maintained?	YES NOX
Overall clean and improved since last inspection. Regular mainter is occurring near fire hydrant should be monitored for sediment ex-	
Debris or sediment accumulation in inlet/catch basin/grate?	YES <u>X</u> NO
If yes, does evidence indicate this is a recent issue?	YES NOX
Is there evidence of sediment/sand/debris tracked into roadway?	YES <u>X</u> NO
If YES, report to supervisor for further investigation or schedule f	or maintenance.
OUTFALL CONDITION:	
Any indications of erosion on bank near associated outfall?	YES NOX
Does associated outfall display evidence sediment passage?	YES NOX

If YES, complete Illicit Discharge Form and submit to supervisor for proper respons

## -Town of Jupiter Inlet Colony-

Site address: <u>168 Beacon Lane</u>	
Date of inspection: <u>November 7<sup>th</sup>, 2018</u>	
Contractor performing the work:	
Is it raining during the inspection?	YES NOX
If NO, date of last rainfall: <u>November 7<sup>th</sup>, 2018</u>	
Is this inspection Pre, During, or Post Construction:D	During Construction
INSPECTION:	
Does this site include the appropriate erosion control?	YES <u>X</u> NO
If yes, what measures have been implemented? Post covered with plywood to reduce trace	-
Are these measures properly installed or maintained?	YES <u>X</u> NO
Debris or sediment accumulation in inlet/catch basin/grate?	YES NOX
If yes, does evidence indicate this is a recent issue?	YES NOX
Is there evidence of sediment/sand/debris tracked into roadway?	YES NO <u>X</u>
If YES, report to supervisor for further investigation or schedule	for maintenance.
OUTFALL CONDITION:	
Any indications of erosion on bank near associated outfall?	VES NO X

Any indications of crosion on bank hear associated outian?	I ES	NO <u>^</u>
Does associated outfall display evidence sediment passage?	YES	NO <u>X</u>

If YES, complete Illicit Discharge Form and submit to supervisor for proper response.

Type of Enforcement Action Taken: <u>None</u> Date to Verify Implementation: <u>N/A</u>

## -Town of Jupiter Inlet Colony-

Site address: <u>176 Beacon Lane</u>	
Date of inspection: <u>November 7<sup>th</sup></u> , 2018	
Contractor performing the work:	
Is it raining during the inspection?	YES NO _X
If NO, date of last rainfall: <u>November 7<sup>th</sup></u> , 2018	_
Is this inspection Pre, During, or Post Construction: Durin	g Construction
INSPECTION:	
Does this site include the appropriate erosion control?	YES NOX
If yes, what measures have been implemented?	
Though there are no current signs of heavy tracking, howe	ever, silt fences would be ideal.
Are these measures properly installed or maintained?	YES NO _X
Debris or sediment accumulation in inlet/catch basin/grate?	YES NO _X
If yes, does evidence indicate this is a recent issue?	YES NO _X
Is there evidence of sediment/sand/debris tracked into roadway?	YES NO _X
If YES, report to supervisor for further investigation or schedule f	for maintenance.
OUTFALL CONDITION:	

## OUTFALL CONDITION:

Any indications of erosion on bank near associated outfall?	YES NO <u>_X</u> _
Does associated outfall display evidence sediment passage?	YES NO _X
	_

If YES, complete Illicit Discharge Form and submit to supervisor for proper response.

## -Town of Jupiter Inlet Colony-

Site address: 209 Cove Place		
Date of inspection: <u>November 7<sup>th</sup></u> , 2018		
Contractor performing the work:		-
Is it raining during the inspection?	YES	NO <u>X</u>
If NO, date of last rainfall: <u>November 7<sup>th</sup>, 2018</u>		
Is this inspection Pre, During, or Post Construction:D	uring Cou	nstruction
INSPECTION:		
Does this site include the appropriate erosion control?	YES _	NOX
If yes, what measures have been implemented? $\underline{i}$		or silt fences should be ted to control tracking.
Are these measures properly installed or maintained?	YES	NO <u>X</u>
Debris or sediment accumulation in inlet/catch basin/grate?	YES _	NO <u>_X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES _	<u>X</u> NO
If YES, report to supervisor for further investigation or schedule f	or mainte	enance.
OUTFALL CONDITION:		

Any indications of erosion on bank near associated outfall?	YES	NO	<u>X</u>
Does associated outfall display evidence sediment passage?	YES	NO _	<u>X</u>

If YES, complete Illicit Discharge Form and submit to supervisor for proper respons

## -Town of Jupiter Inlet Colony-

Site address: 243 Ocean Drive (by Beach Club)	
Date of inspection: <u>November 7<sup>th</sup>, 2018</u>	
Contractor performing the work:	
Is it raining during the inspection?	YES NOX
If NO, date of last rainfall: <u>November 7<sup>th</sup>, 2018</u>	
Is this inspection Pre, During, or Post Construction:D	uring Construction
INSPECTION:	
Does this site include the appropriate erosion control?	YES <u>X</u> NO
If yes, what measures have been implemented?	ences and graveling
Are these measures properly installed or maintained?	YES NOX
Silt fence has multiple rips that need repair. Grass/sod and grave and are impairing flow.	l have invaded the valley gutter
Debris or sediment accumulation in inlet/catch basin/grate?	YES NO _X
If yes, does evidence indicate this is a recent issue?	YES NO _X
Is there evidence of sediment/sand/debris tracked into roadway?	YES NO _X
If YES, report to supervisor for further investigation or schedule	for maintenance.
OUTFALL CONDITION:	
Any indications of erosion on bank near associated outfall?	YES NOX

If YES, complete Illicit Discharge Form and submit to supervisor for proper response.

YES \_\_\_\_\_ NO \_\_X\_\_\_

Type of Enforcement Action Taken: <u>Will advise Chief John</u> Date to Verify Implementation: <u>Dec. Monthly Inspection</u>

Does associated outfall display evidence sediment passage?

# Grass Swale – Structural Control Inspection

- Town of Jupiter Inlet Colony –

Facility/Segment ID:	Town Grass Swales	Date:	<u>November 7<sup>th</sup>, 2018</u>	
FUNCTION:				
Wet Bottom?			YES NO <u>_X</u>	
Aquatic vegetation present	?		YES NO _X	
Dead or dying grass on bot	tom?		YES NO $\underline{X}$	
If YES, report to supervisor	r for further investigation of	or schedule for	maintenance.	
EROSION:				
Vegetation on bottom or sid	de slopes failing?		YES NO _X	
Any signs of erosion?			YES NOX	
If YES, describe and schedu	ile for maintenance:			
GENERAL:				_
Any signs of damage from pa	0		YES NO _X	
Any fences or other objects th	nat could obstruct flow into/tl	hrough the swale	e? YES NO <u>_X</u>	
If YES, describe and report to	supervisor for proper respon	nse:		

## Proactive Illicit Discharge/Illegal Connection Inspection Form - Town of Jupiter Inlet Colony -

Date of Inspection: <u>November 7<sup>th</sup>, 2018</u> Address of Facility OR General Description of Area Inspected: <u></u> Identification of MS4 component that could receive discharge from	
If facility inspection, does type of business require an MSGP?	YES NO _X
If yes, does this facility have one?	YES NO
Findings:	
Evidence of illicit connections to storm sewer?	YES NO $\underline{X}$
Evidence of dumping/spills to storm sewer?	YES NO _X
Evidence of wash water going to storm sewer?	YES NO _X
Storage tanks leaking or improperly contained?	YES NO _X
Stockpiles/debris piles uncontained?	YES NO <u>_X</u>
If "YES," to any above, describe:	

Type of Enforcement Action Taken: None

Date to verify elimination:

Date of Referral to FDEP of facility that may require MSGP: \_\_\_\_\_

# Inlets/Catch Basins/Grates – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID: General Town Inlets/Catch Basins/Grates

Date: \_ November 7<sup>th</sup>, 2018\_\_\_\_\_

Is it raining during the inspec	tion?	YES	NOX
If NO, date of last rainfall:	November 7 <sup>th</sup> , 2018		

#### **FUNCTION:**

Debris or sediment accumulation in inlet/catch basin/grate?	? YES	_ NO _ <u>X</u>
Barnacle accumulation in inlet/catch basin/grate?	YES	_ NO <u>_X</u> _
Sediment accumulation in inlet/catch basin/grate?	YES	_ NO _ <u>X</u> _
Evidence of settling of pipe – misalignment?	YES	_NO <u>X</u> _
Inlet/catch basin/grate in need of repair/replacement?	YES	_NO <u>X</u> _

If YES, report to supervisor for further investigation or schedule for maintenance.

#### **ILLICIT DISCHARGE INDICATIONS:**

Any indications of illicit discharge or illegal dumping? YES \_\_\_\_ NO \_X\_\_

If YES, complete illicit Discharge Inspection Form and submit to supervisor or proper response.

#### NOTES:

Minor vegetative debris was observed in several inlets but not to the point of deterring flow. There are several areas in the neighborhood gutters that are experiencing significant sediment from construction. Specifics have been included in the construction site inspection reports.

## Major Stormwater Outfall #2 – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID: JIC-Outfall #2 (103 Lighthouse D	Drive) Date: November 7 <sup>th</sup> , 2018
Is it raining during the inspection? If NO, date of last rainfall:	YES NO _X November 7 <sup>th</sup> , 2018
PIPE FLOWING:	YES <u>X</u> NO
If YES, check appropriate box:	
Flow was probably of	due to high tide which occurred at 7:57 a.m.
E11 I	Vine Flow

Full Pipe Flow □ <sup>3</sup>⁄<sub>4</sub> Pipe Flow ⊠ <sup>1</sup>⁄<sub>2</sub> Pipe Flow □

1/4 Pipe Flow  $\Box$ 

If YES, report to supervisor for further investigation or schedule for maintenance.

#### **FUNCTION:**

Debris or sediment accumulation in pipe? Barnacle accumulation in pipe?	YES NOX YESX NO Accumulation on exterior
Sediment accumulation in receiving water?	YES NOX
Pipe in need of repair/replacement?	YES NOX
Headwall in need of repair/replacement?	YES NOX

If YES, report to supervisor for further investigation or schedule for maintenance.

#### **EROSION:**

Signs of Erosion on bank near outfall?	YES NOX
Rip-rap in need of maintenance?	YES NOX

If YES, report to supervisor for further investigation or schedule for maintenance.

### **ILLICIT DISCHARGE INDICATIONS:**

Any indications of illicit discharge or illegal dumping? YES \_\_\_\_\_ NO \_\_\_X\_\_\_

## Major Stormwater Outfall #3 – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID: JIC-Outfall #3 (87 Lighthouse Drive) Date: November 7<sup>th</sup>, 2018

Is it raining during the inspection? YES \_\_\_\_\_ NO \_X\_\_\_ If NO, date of last rainfall: \_\_\_November 7<sup>th</sup>, 2018\_\_\_\_

#### **PIPE FLOWING:**

Pipe submerged due to high tide. According to records, high tide was at 7:57 a.m.

If YES, check appropriate box:

Full Pipe Flow □ <sup>3</sup>⁄<sub>4</sub> Pipe Flow ⊠ <sup>1</sup>⁄<sub>2</sub> Pipe Flow □ <sup>1</sup>⁄<sub>4</sub> Pipe Flow □

If YES, report to supervisor for further investigation or schedule for maintenance.

#### **FUNCTION:**

Debris or sediment accumulation in pipe?	YES NO _ <u>X</u> _
Barnacle accumulation in pipe?	YES <u>X</u> NO
	Some accumulation on outside of pipe.
Sediment accumulation in receiving water?	YES NOX
Pipe in need of repair/replacement?	YES NOX
Headwall in need of repair/replacement?	YES NOX

If YES, report to supervisor for further investigation or schedule for maintenance.

### **EROSION:**

Signs of Erosion on bank near outfall?	YES	NO <u>X</u>
Rip-rap in need of maintenance?	YES	NO <u>X</u>
If VES report to supervisor for further invest	tigation or sche	Jula for maintan

## If YES, report to supervisor for further investigation or schedule for maintenance.

### **ILLICIT DISCHARGE INDICATIONS:**

Any indications of illicit discharge or illegal dumping? YES \_\_\_\_\_ NO \_\_X\_\_

If YES, complete Illicit Discharge Inspection Form and submit to supervisor for proper response.

YES \_\_\_\_ NO \_X\_

## Major Stormwater Outfall #4 – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID:IC-Outfall #4 (75 Light	thouse Drive) Date: <u>November 7<sup>th</sup>, 2018</u>				
Is it raining during the inspection? If NO, date of last rainfall: _	YESNOX November 7 <sup>th</sup> , 2018				
PIPE FLOWING:	YES NOX				
If YES, check appropriate box:					
Full Pipe Flow					
	<sup>3</sup> ⁄4 Pipe Flow □				
	<sup>1</sup> ⁄ <sub>2</sub> Pipe Flow □				
	<sup>1</sup> ⁄ <sub>4</sub> Pipe Flow □				
If YES, report to supervisor for further investigation or schedule for maintenance.					

#### **FUNCTION:**

Debris or sediment accumulation in pipe?	YES	NO X
Barnacle accumulation in pipe?	YES	_NO <u>X</u>
Sediment accumulation in receiving water?	YES	_NO <u>X</u>
Pipe in need of repair/replacement?	YES	_NO <u>X</u>
Headwall in need of repair/replacement?	YES	_NO <u>X</u>

If YES, report to supervisor for further investigation or schedule for maintenance.

#### **EROSION:**

Signs of Erosion on bank near outfall?	YES	_NO_	<u>X</u>				
Rip-rap in need of maintenance?	YES	_NO_	<u>X</u>				
If YES, report to supervisor for further investigation or schedule for maintenance.							

#### **ILLICIT DISCHARGE INDICATIONS:**

Any indications of illicit discharge or illegal dumping? YES \_\_\_\_\_ NO \_\_X\_\_\_

If YES, complete Illicit Discharge Inspection Form and submit to supervisor for proper response.

## Major Stormwater Outfall #5 – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID: <u>JIC-Outfall #5 (Beach Cl</u>	ub) Date: <u>November 7<sup>th</sup>, 2018</u>				
Is it raining during the inspection? If NO, date of last rainfall:	YESNOX November 7 <sup>th</sup> , 2018				
PIPE FLOWING:	YES NOX				
If YES, check appropriate box:					
	Full Pipe Flow $\Box$				
	¾ Pipe Flow □				
	<sup>1</sup> /2 Pipe Flow $\Box$				
	<sup>1</sup> ⁄ <sub>4</sub> Pipe Flow □				

If YES, report to supervisor for further investigation or schedule for maintenance.

#### **FUNCTION:**

Debris or sediment accumulation in pipe?	YES NOX
Barnacle accumulation in pipe?	YES NOX
Sediment accumulation in receiving water?	YES NOX
Pipe in need of repair/replacement?	YES NOX
Headwall in need of repair/replacement?	YES NOX

If YES, report to supervisor for further investigation or schedule for maintenance.

#### **EROSION:**

Signs of Erosion on bank near outfall?					YES	NO	<u>X</u>				
Rip-rap in	need of m	aintena	ince	?				YES	NO	<u>X</u>	
		•	c	c	.1	•		 1	110	• ,	

If YES, report to supervisor for further investigation or schedule for maintenance.

### **ILLICIT DISCHARGE INDICATIONS:**

Any indications of illicit discharge or illegal dumping? YES \_\_\_\_\_ NO \_\_\_X\_\_\_

If YES, complete Illicit Discharge Inspection Form and submit to supervisor for proper response.