Site address: 12 Ocean Drive	_	
Date of inspection:		
Contractor performing the work:		
Is it raining during the inspection?	YES	_NO _ <u>X</u>
If NO, date of last rainfall:January 3 rd , 2018		
Is this inspection Pre, During, or Post Construction:Du	ring Cons	truction_
INSPECTION:		
Does this site include the appropriate erosion control?	YES X	_NO
If yes, what measures have been implemented? Silt Fence		
Are these measures properly installed or maintained?	YES X	NO
Fence is properly maintained; however sediment has continued to gutter. Applying gravel to areas of loose soil would help control the		e in the valley
Debris or sediment accumulation in inlet/catch basin/grate?	YES	_NO _ <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO _ <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES X	_ NO
If YES, report to supervisor for further investigation or schedule for	or mainten	ance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES	NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES	NO <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for proper	response.
Type of Enforcement Action Taken: Will report to Police Chief Jo	ohn Pruitt	
Date to Verify Implementation: Feb. Monthly Inspection		

Site address: 14 Ocean Drive	_		
Date of inspection:			
Contractor performing the work:			
Is it raining during the inspection?	YES _	NO _	<u>X</u>
If NO, date of last rainfall:January 3 rd , 2019			
Is this inspection Pre, During, or Post Construction: Post	ost Constr	uction_	
INSPECTION:			
Does this site include the appropriate erosion control?	YES	NO _	X
If yes, what measures have been implemented?			
Are these measures properly installed or maintained?	YES	NO	<u>X</u>
All sodding is complete. Site is clean of debris and will be remove	ed from o	ur inspec	tion list
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO	<u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO _	<u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES	NO _	<u>X</u>
If YES, report to supervisor for further investigation or schedule	for mainte	nance.	
OUTFALL CONDITION:			
Any indications of erosion on bank near associated outfall?	YES	NO	<u>X</u>
Does associated outfall display evidence sediment passage?	YES	NO	<u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prope	r respons	se
Type of Enforcement Action Taken: None.			
Date to Verify Implementation: None.			

Site address: 32 Ocean Drive (Blue House)			
Date of inspection: <u>January 9th</u> , <u>2019</u>			
Contractor performing the work:			
Is it raining during the inspection?	YES	NO	<u>X</u>
If NO, date of last rainfall:January 3 rd , 2019			
Is this inspection Pre, During, or Post Construction: Post Construction:	Constructi	<u>on</u>	
INSPECTION:			
Does this site include the appropriate erosion control?	YES	XNO_	
If yes, what measures have been implemented?			
Are these measures properly installed or maintained?	YES	X_NO	
Construction is complete, site is clean of all debris. This site will inspection list.	now be re	moved from	om our
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO _	<u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO _	<u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES	NO _	<u>X</u>
If YES, report to supervisor for further investigation or schedule f	for mainte	nance.	
OUTFALL CONDITION:			
Any indications of erosion on bank near associated outfall?	YES	NO _	<u>X</u>
Does associated outfall display evidence sediment passage?	YES	NO _	<u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prope	r respons	
Type of Enforcement Action Taken: None			
Date to Verify Implementation: None			

Site address: 47 Ocean Drive		
Date of inspection:		
Contractor performing the work:		_
Is it raining during the inspection?	YES _	NO <u>X</u>
If NO, date of last rainfall:January 3 rd , 2019		
Is this inspection Pre, During, or Post Construction:D	uring Co	nstruction_
INSPECTION:		
Does this site include the appropriate erosion control?	YES _	NO _ <u>X</u>
If yes, what measures have been implemented?None		
Are these measures properly installed or maintained?	YES _	<u>X</u> NO
Earthwork just began on site. Site was clean but no erosion control	ol is curr	ently installed.
Debris or sediment accumulation in inlet/catch basin/grate?	YES _	NO <u>_X</u> _
If yes, does evidence indicate this is a recent issue?	YES _	NO <u>_X</u> _
Is there evidence of sediment/sand/debris tracked into roadway?	YES _	NO <u>X</u> _
If YES, report to supervisor for further investigation or schedule f	for main	tenance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES _	NO _ <u>X</u>
Does associated outfall display evidence sediment passage?	YES _	NO <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prop	er response.
Type of Enforcement Action Taken: None		
Date to Verify Implementation: None		

Site address: <u>59 Colony Road</u>		
Date of inspection: <u>January 9th</u> , 2019		
Contractor performing the work:		
Is it raining during the inspection?	YES _	NO <u>X</u>
If NO, date of last rainfall:January 3 rd , 2019	_	
Is this inspection Pre, During, or Post Construction: _Duri	ng Const	ruction_
INSPECTION:		
Does this site include the appropriate erosion control?	YES _	<u>X</u> NO
If yes, what measures have been implemented?		
Though no silt fence or graveling has been implemented, site is cl Graveling or other tracking prevention would be ideal.	ean and v	vell maintained.
Are these measures properly installed or maintained?	YES _	<u>X</u> NO
Debris or sediment accumulation in inlet/catch basin/grate?	YES _	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES _	NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES _	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule f	or mainte	enance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES _	NO _ <u>X</u>
Does associated outfall display evidence sediment passage?	YES _	NO _ <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prope	er respons
Type of Enforcement Action Taken: None		
Date to Verify Implementation: None		

Site address: 82 Lighthouse Drive		
Date of inspection: <u>January 9th</u> , 2019		
Contractor performing the work:		-
Is it raining during the inspection?	YES _	NO <u>X</u>
If NO, date of last rainfall:January 3 rd , 2019		-
Is this inspection Pre, During, or Post Construction:D	uring Con	nstruction_
INSPECTION:		
Does this site include the appropriate erosion control?	YES _	<u>X</u> _ NO
If yes, what measures have been implemented?		
Though no silt fence or graveling installed, the site was clean and evidence of tracking. Regular maintenance should suffice.	well mai	ntained. Some
Are these measures properly installed or maintained?	YES _	<u>X</u> NO
Debris or sediment accumulation in inlet/catch basin/grate?	YES _	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES _	NO _ <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES _	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule	for mainte	enance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES _	NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES _	NO _ <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prope	er respons
Type of Enforcement Action Taken: None		
Date to Verify Implementation: None		

Site address: 100 Lighthouse Drive (Gym Construction)		
Date of inspection: <u>January 9th</u> , 2019		
Contractor performing the work:		_
Is it raining during the inspection?	YES _	NO <u>X</u>
If NO, date of last rainfall:January 3 rd , 2019	_	
Is this inspection Pre, During, or Post Construction:Du	aring Co	onstruction_
INSPECTION:		
Does this site include the appropriate erosion control?	YES _	<u>X</u> _ NO
If yes, what measures have been implemented?		
Are these measures properly installed or maintained?	YES_	<u>X</u> NO
Plywood is in-tact and site is clean. Regular maintenance should s	uffice.	
Debris or sediment accumulation in inlet/catch basin/grate?	YES_	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES _	NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES_	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule for	or main	tenance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES _	NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES _	NO <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prop	er respons
Type of Enforcement Action Taken: None		
Date to Verify Implementation: None		

Site address: 102 Lighthouse Drive (Empty Lot)		_
Date of inspection: January 9th, 2019		
Contractor performing the work:		_
Is it raining during the inspection?	YES _	NO <u>X</u>
If NO, date of last rainfall:January 3 rd , 2019		
Is this inspection Pre, During, or Post Construction:D	ouring Co	nstruction_
INSPECTION:		
Does this site include the appropriate erosion control?	YES _	<u>X</u> NO
If yes, what measures have been implemented?		
Are these measures properly installed or maintained?	YES _	<u>X</u> NO
Silt Fence has been implemented but still some evidence of track by cars turning around in open space.	ing. Trac	king is likely caused
Debris or sediment accumulation in inlet/catch basin/grate?	YES _	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES _	NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES _	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule	for maint	tenance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES _	NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES _	NO <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	r for prop	er respons
Type of Enforcement Action Taken: None		
Date to Verify Implementation: None		

-Town of Jupiter Inlet Colony-

Site address: 116 Lighthouse Drive (previously recorded as 99)		
Date of inspection: <u>January 9th</u> , 2019		
Contractor performing the work:		
Is it raining during the inspection?	YES	NO <u>X</u>
If NO, date of last rainfall:January 3 rd , 2019	_	
Is this inspection Pre, During, or Post Construction:D	uring Con	struction_
INSPECTION:		
Does this site include the appropriate erosion control?	YES	NO <u>X</u>
If yes, what measures have been implemented?		
Site is clean, but no graveling or fencing is implemented.	Some evic	dence of tracking.
Are these measures properly installed or maintained?	YES	NO <u>X</u>
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO _ <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule f	or mainte	nance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES	NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES	NO <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prope	r respons
-		-

Date to Verify Implementation: Feb. Monthly Inspection

Type of Enforcement Action Taken: Will notify Chief John

-Town of Jupiter Inlet Colony-

Site address: 126 Lighthouse Drive	_		
Date of inspection: <u>January 9th</u> , 2019			
Contractor performing the work:		_	
Is it raining during the inspection?	YES _	NO	<u>X</u>
If NO, date of last rainfall:January 3 rd , 2019			
Is this inspection Pre, During, or Post Construction:D	uring Co	nstruction_	
INSPECTION:			
Does this site include the appropriate erosion control?	YES _	X_ NO	
If yes, what measures have been implemented?			
Are these measures properly installed or maintained?	YES _	X_NO	
Minor amounts of gravel have infiltrated roadway. Regular maintenance should continue.	enance o	f fence and	d graveling
Debris or sediment accumulation in inlet/catch basin/grate?	YES _	NO	<u>X</u>
If yes, does evidence indicate this is a recent issue?	YES _	NO _	<u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES _	NO	<u>X</u>
If YES, report to supervisor for further investigation or schedule f	or maint	enance.	
OUTFALL CONDITION:			
Any indications of erosion on bank near associated outfall?	YES _	NO _	<u>X</u>
Does associated outfall display evidence sediment passage?	YES _	NO _	<u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prop	er respons	
Type of Enforcement Action Taken: Will notify Chief John			

Date to Verify Implementation: Feb. Monthly Inspection

-Town of Jupiter Inlet Colony-

Site address: <u>168 Beacon Lane</u>		
Date of inspection:		
Contractor performing the work:		
Is it raining during the inspection?	YES	NO <u>X</u>
If NO, date of last rainfall:January 3 rd , 2019		
Is this inspection Pre, During, or Post Construction:D	uring Con	struction_
INSPECTION:		
Does this site include the appropriate erosion control?	YES	NO <u>X</u>
If yes, what measures have been implemented?		
No current erosion control installed (i.e. fence, graveling, clean.	olywood)	. Site was overall
Are these measures properly installed or maintained?	YES	NO <u>X</u>
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES _	NO <u>X</u>
If YES, report to supervisor for further investigation or schedule f	or mainte	enance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES	_NO _ <u>X</u>
Does associated outfall display evidence sediment passage?	YES	_ NO <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for prope	er response.
Type of Enforcement Action Taken: Will notify Chief John Pruit	<u>t</u>	

Date to Verify Implementation: Feb. Monthly Inspection

Site address: <u>176 Beacon Lane</u>	
Date of inspection:	
Contractor performing the work:	
Is it raining during the inspection?	YES NO _ <u>X</u> _
If NO, date of last rainfall:January 3 rd , 2019	<u> </u>
Is this inspection Pre, During, or Post Construction: Post Construction:	Construction
INSPECTION:	
Does this site include the appropriate erosion control?	YES <u>X</u> NO
If yes, what measures have been implemented?	
All sodding has been placed and site is clean of all debris. This sit our inspection list.	te will now be removed from
Are these measures properly installed or maintained?	YES X_ NO _
Debris or sediment accumulation in inlet/catch basin/grate?	YES NO _ <u>X</u> _
If yes, does evidence indicate this is a recent issue?	YES NO _ <u>X</u> _
Is there evidence of sediment/sand/debris tracked into roadway?	YES NO _ <u>X</u> _
If YES, report to supervisor for further investigation or schedule f	for maintenance.
OUTFALL CONDITION:	
Any indications of erosion on bank near associated outfall?	YES NO _ <u>X</u> _
Does associated outfall display evidence sediment passage?	YES NO _ <u>X</u> _
If YES, complete Illicit Discharge Form and submit to supervisor	for proper response.
Type of Enforcement Action Taken: None	
Date to Verify Implementation: None	

Site address: <u>187 Shelter Lane</u>			
Date of inspection:			
Contractor performing the work:		-	
Is it raining during the inspection?	YES _	NO <u>X</u>	
If NO, date of last rainfall:January 3 rd , 2019			
Is this inspection Pre, During, or Post Construction:D	uring Co	nstruction_	
INSPECTION:			
Does this site include the appropriate erosion control?	YES _	NO <u>X</u>	
If yes, what measures have been implemented?			
Are these measures properly installed or maintained?	YES _	<u>X</u> NO	
Site is early on in construction process. All construction is be	hind driv	veway and site is cle	<u>an.</u>
Debris or sediment accumulation in inlet/catch basin/grate?	YES _	NO _ <u>X</u>	
If yes, does evidence indicate this is a recent issue?	YES _	NO <u>_X</u> _	
Is there evidence of sediment/sand/debris tracked into roadway?	YES _	NO _ <u>X</u> _	
If YES, report to supervisor for further investigation or schedule f	or maint	enance.	
OUTFALL CONDITION:			
Any indications of erosion on bank near associated outfall?	YES _	NO <u>X</u>	
Does associated outfall display evidence sediment passage?	YES _	NO <u>X</u>	
If YES, complete Illicit Discharge Form and submit to supervisor	for prop	er response.	
Type of Enforcement Action Taken: None			
Date to Verify Implementation: None			

Site address: <u>189 Shelter Lane</u>		
Date of inspection:		
Contractor performing the work:		
Is it raining during the inspection?	YES NO _ <u>X</u>	
If NO, date of last rainfall:January 3 rd , 2019	_	
Is this inspection Pre, During, or Post Construction:D	uring Construction_	
INSPECTION:		
Does this site include the appropriate erosion control?	YES NOX	
If yes, what measures have been implemented?		
Are these measures properly installed or maintained?	YES _ <u>X</u> NO	
Site is early in construction phase. Site is overall clean.		
Debris or sediment accumulation in inlet/catch basin/grate?	YES NO _ <u>X</u> _	
If yes, does evidence indicate this is a recent issue?	YES NO <u>_X</u> _	
Is there evidence of sediment/sand/debris tracked into roadway? YES NO _X_		
If YES, report to supervisor for further investigation or schedule f	for maintenance.	
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES NOX	
Does associated outfall display evidence sediment passage?	YES NOX	
If YES, complete Illicit Discharge Form and submit to supervisor	for proper response.	
Type of Enforcement Action Taken: None		
Date to Verify Implementation: None		

-Town of Jupiter Inlet Colony-

Site address: 213 Treasure Place (Previously marked 209 Cove P	lace)	
Date of inspection: <u>January 9th</u> , <u>2019</u>		
Contractor performing the work:		
Is it raining during the inspection?	YES	_NO <u>X</u>
If NO, date of last rainfall:January 3 rd , 2019		
Is this inspection Pre, During, or Post Construction:D	uring Const	truction
INSPECTION:		
Does this site include the appropriate erosion control?	YESX	NO
If yes, what measures have been implemented?		
Overall site was clean, but could use regular maintenance or impletracking prevention.	ementation ementation	of sediment
Are these measures properly installed or maintained?	YES X	NO
Debris or sediment accumulation in inlet/catch basin/grate?	YES	_NO <u>X</u>
If yes, does evidence indicate this is a recent issue?	YES	NO _ <u>X</u>
Is there evidence of sediment/sand/debris tracked into roadway?	YES	_ NO <u>X</u>
If YES, report to supervisor for further investigation or schedule f	or mainten	ance.
OUTFALL CONDITION:		
Any indications of erosion on bank near associated outfall?	YES	NO <u>X</u>
Does associated outfall display evidence sediment passage?	YES	NO <u>X</u>
If YES, complete Illicit Discharge Form and submit to supervisor	for proper	response.
Type of Enforcement Action Taken: None		

Date to Verify Implementation: None

Site address: 243 Ocean Drive (by Beach Club)	_
Date of inspection:	
Contractor performing the work:	
Is it raining during the inspection?	YES NOX
If NO, date of last rainfall:January 3 rd , 2019	_
Is this inspection Pre, During, or Post Construction:D	uring Construction_
INSPECTION:	
Does this site include the appropriate erosion control?	YES <u>X</u> NO
If yes, what measures have been implemented?Silt fe	ences and graveling
Are these measures properly installed or maintained?	YES <u>X</u> NO
Overall site was in good condition. Some gravel and sediment trace Regular maintenance should continue.	cking into the valley gutter
Debris or sediment accumulation in inlet/catch basin/grate?	YES NO <u>X</u> _
If yes, does evidence indicate this is a recent issue?	YES NO <u>X</u> _
Is there evidence of sediment/sand/debris tracked into roadway?	YES NO <u>X</u> _
If YES, report to supervisor for further investigation or schedule f	for maintenance.
OUTFALL CONDITION:	
Any indications of erosion on bank near associated outfall?	YES NOX
Does associated outfall display evidence sediment passage?	YES NOX
If YES, complete Illicit Discharge Form and submit to supervisor	for proper response.
Type of Enforcement Action Taken: None	
Date to Verify Implementation: None	

Grass Swale – Structural Control Inspection

Facility/Segment ID: _	Town Grass Swales	Date:	January 9th,20	<u> 19</u>
FUNCTION:				
Wet Bottom?			YES	NO X
Aquatic vegetation present?			YES	NO X
Dead or dying grass on botto	m?		YES	NO X NO X NO X
If YES, report to supervisor f	for further investigation or	schedule for	maintenance.	
EROSION:				
Vegetation on bottom or side	slopes failing?		YES	NO <u>X</u>
Any signs of erosion?			YES	NO X NO X
If YES, describe and schedule	e for maintenance:			
GENERAL:				
Any signs of damage from park Any fences or other objects that	ring in swale?		YES	NO _ <u>X</u>
Any fences or other objects that	t could obstruct flow into/thre	ough the swale	e? YES	NO <u>X</u>
If YES, describe and report to s	upervisor for proper response	e:		

Proactive Illicit Discharge/Illegal Connection Inspection Form - Town of Jupiter Inlet Colony -

Date of Inspection:						
Address of Facility OR General Description of Area Inspected:	General	Town				
Identification of MS4 component that could receive discharge from	om this site	e/area:				
-						
If facility inspection, does type of business require an MSGP?	YES	NO <u>_X</u> _				
If yes, does this facility have one?	YES	NO				
Findings:						
Evidence of illicit connections to storm sewer?	YES	NO X				
Evidence of dumping/spills to storm sewer?	YES					
Evidence of wash water going to storm sewer?	YES	NO _ <u>X</u>				
Storage tanks leaking or improperly contained? YES $\underline{\hspace{1cm}}$ NO $\underline{\hspace{1cm}}$						
Stockpiles/debris piles uncontained? YES NO X						
If "YES," to any above, describe:						
Type of Enforcement Action Taken: None						
Date to verify elimination:						
Date of Referral to FDEP of facility that may require MSGP:						

Inlets/Catch Basins/Grates – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID: General Town Inlets/Catch Basins/Grates	-	
Date:January 9th, 2019		
Is it raining during the inspection?	YES	NO_X_
If NO, date of last rainfall:January 3 rd , 2019	_	
FUNCTION:		
Debris or sediment accumulation in inlet/catch basin/grate?	YES	NO X
Barnacle accumulation in inlet/catch basin/grate?	YES	
Sediment accumulation in inlet/catch basin/grate?	YES	NO X
Evidence of settling of pipe – misalignment?	YES	NO X
Inlet/catch basin/grate in need of repair/replacement?	YES	NO X
If YES, report to supervisor for further investigation or sche	edule for m	aintenance.
ILLICIT DISCHARGE INDICATIONS: Any indications of illicit discharge or illegal dumping?	YES	NO X
If YES, complete illicit Discharge Inspection Form and suresponse.	ıbmit to sı	pervisor or proper
NOTES:		

Major Stormwater Outfall #2 – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID: JIC-Outfall #2 (103 Lighth	ouse Drive)		Date:	<u>Januar</u>	y 9 th , 2	<u>2019</u>
Is it raining during the inspection?		YES		NO _	<u>X</u>	
If NO, date of last rainfall: _	January 3	3rd, 201	9			
PIPE FLOWING:		YES	<u>X</u> _	NO_		
If YES, check appropriate box:						
	Full Pipe Flow					
	³ ⁄ ₄ Pipe Flow □					
	½ Pipe Flow □					
	Less than 1/4 Pipe	e Flow	\boxtimes			
If YES, report to supervisor for furth FUNCTION: Debris or sediment accumulation in Barnacle accumulation in pipe? Sediment accumulation in receiving Pipe in need of repair/replacement? Headwall in need of repair/replacem	pipe?	YES YES	X Accu	NO_ NO	X ion on	exterio
If YES, report to supervisor for furt	her investigation	n or sc	hedul	le for n	nainte	nance.
EROSION:	110	MEG		NO	37	
Signs of Erosion on bank near outfal Rip-rap in need of maintenance?	11?	YES YES		NO _ NO _	<u>X</u> <u>X</u>	
If YES, report to supervisor for furt	her investigation	n or sc	hedul	le for n	nainte	nance.
ILLICIT DISCHARGE INDIC Any indications of illicit discharge or i		YES _]	NO	<u>X</u>	

Major Stormwater Outfall #3 – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID:JIC-Outfall #3 (87 Lighthouse Dr	Date: January 9th, 2019
Is it raining during the inspection? If NO, date of last rainfall:	YESNO _X
PIPE FLOWING:	YES NO _ <u>X</u>
If YES, check appropriate box:	
Full Pipe	e Flow □
³ / ₄ Pipe F	Flow □
½ Pipe F	Flow □
1/4 Pipe F	Flow
If YES, report to supervisor for further inves	tigation or schedule for maintenance.
FUNCTION:	VEG NO V
Debris or sediment accumulation in pipe? Barnacle accumulation in pipe?	YES NO X NO Some accumulation on outside of pipe.
Sediment accumulation in receiving water?	YES NO X
Pipe in need of repair/replacement?	YES NO X
Headwall in need of repair/replacement?	YESNO _X
If YES, report to supervisor for further inves	tigation or schedule for maintenance.
EROSION:	
Signs of Erosion on bank near outfall?	YESNO _X_
Rip-rap in need of maintenance? If YES, report to supervisor for further inves	YES NO _X
ILLICIT DISCHARGE INDICATION Any indications of illicit discharge or illegal dun	
If YES, complete Illicit Discharge Inspecti proper response.	on Form and submit to supervisor for

Major Stormwater Outfall #4 – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID: <u>JIC-Outfall #4 (75 Lighthouse</u>	ouse Drive) Date: _January 9th, 2019
Is it raining during the inspection? If NO, date of last rainfall:	YES NOX January 3 rd , 2019
PIPE FLOWING:	YES NO <u>X</u>
If YES, check appropriate box:	
1	Full Pipe Flow □
3	² ⁄ ₄ Pipe Flow □
!	∕₂ Pipe Flow □
!	∕4 Pipe Flow □
If YES, report to supervisor for further	er investigation or schedule for maintenance.
FUNCTION: Debris or sediment accumulation in parnacle accumulation in pipe? Sediment accumulation in receiving value in need of repair/replacement? Headwall in need of repair/replacement. If YES, report to supervisor for further.	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$
EROSION: Signs of Erosion on bank near outfall' Rip-rap in need of maintenance? If YES, report to supervisor for furthe	YES NO _X YES NO _X r investigation or schedule for maintenance.
ILLICIT DISCHARGE INDICA Any indications of illicit discharge or ill	
If YES, complete Illicit Discharge la proper response.	Inspection Form and submit to supervisor for

Major Stormwater Outfall #5 – Structural Control Inspection -Town of Jupiter Inlet Colony-

Facility ID: <u>JIC-Outfall #5 (Beach Club)</u>	Date: <u>January 9th</u> , 2019
Is it raining during the inspection?	YES NO <u>X</u>
If NO, date of last rainfall:	January 3 rd , 2019
PIPE FLOWING:	YES NO <u>X</u>
If YES, check appropriate box:	
Fu	ıll Pipe Flow □
3/4	Pipe Flow ⊠
1/2	Pipe Flow □
	Pipe Flow □
	1
If YES, report to supervisor for further	investigation or schedule for maintenance.
FUNCTION:	
Debris or sediment accumulation in pip	oe? YES NO _X
Barnacle accumulation in pipe?	YES NO <u>X</u>
Sediment accumulation in receiving wa	
Pipe in need of repair/replacement?	YES NO <u>X</u>
Headwall in need of repair/replacemen	
• •	investigation or schedule for maintenance.
EROSION:	VEC NO V
Signs of Erosion on bank near outfall? Rip-rap in need of maintenance?	YES NOX_ YES NOX_
	investigation or schedule for maintenance.
ii 122, report to supervisor for furtion	in testigation of senedule for manifestance.
ILLICIT DISCHARGE INDICAT	ΓIONS:
Any indications of illicit discharge or illeg	gal dumping? YESNOX
If VFS complete Illicit Discharge Inc	spection Form and submit to supervisor for
proper response.	specific Form and submit to supervisor for