

TV Inspection Report

MH CB133 to CB134 Downstream Inspection

PSR CB133-CB134	PO number	Status Completed	Date 11/05/2018	Time 34:03 PM	Weather Dry
---------------------------	-----------	----------------------------	---------------------------	-------------------------	-----------------------

Street corner of Date Palm Dr and Lake Shore Dr	City Lake Shore	Owner
---	---------------------------	-------

Customer	Surveyor Name Marvin Vicente	Cert # U-0817-07008912	Length Surveyed 33.9	Total Length
----------	--	----------------------------------	--------------------------------	--------------

Location Code Light Highway	Location Details	Ht/Dia 18	Width	Shape Circular	Material RCP	Pre-Cleaning J	Date Cleaned 11/05/2018	Sewer Use SW
Upstream MH CB133	US Rim to Inv	US Grd to Inv	US Rim to Grd	Downstream MH CB134	DS Rim to Inv	DS Grd to Inv	DS Rim to Grd	
Direction Downstream	Flow control Not Control...	Drainage Area	Lining Method	Joint Length	Year Laid	Year Renewed	Sewer Category SW	

Video Name CB133-CB134_46683_11_05_2018.mpg	Media Label	Additional Info	Purpose D	Sheet 1
---	-------------	-----------------	---------------------	-------------------

Optional1	Optional2
Optional3	Optional4
Optional5	Optional6
Optional7	Optional8
Optional9	Optional10

Footage	Code	CD	Observation	At	To	V1	V2	%	Jt	Remarks	Img
<Start Inspection>											
0.0	AMH		Manhole							Starting manhole: CB133	X
0.0	MWL		Water Level					5			X
33.9	AMH		Manhole							Finishing manhole: CB134	X
<Complete Inspection>											