

# TV Inspection Report

## MH CB2 to CB2A Downstream Inspection

<b>PSR</b> CB2-CB2A		PO number	Status	Date	Time	Weather			
			<b>Completed</b>	<b>11/05/2018</b>	<b>:56:27 AM</b>	<b>Dry</b>			
Street			City		Owner				
corner of E Ilex Dr and Lake Shore Dr			Lake Shore						
Customer		Surveyor Name		Cert #		Length Surveyed Total Length			
		<b>Marvin Vicente</b>		<b>U-0817-07008912</b>		<b>164.7</b>			
Location Code	Location Details		Ht/Dia	Width	Shape	Material	Pre-Cleaning	Date Cleaned	Sewer Use
<b>Light Highway</b>			<b>24</b>		<b>Circular</b>	<b>RCP</b>	<b>N</b>	<b>11/05/2018</b>	<b>SW</b>
Upstream MH	US Rim to Inv	US Grd to Inv	US Rim to Grd	Downstream MH	DS Rim to Inv	DS Grd to Inv	DS Rim to Grd		
<b>CB2</b>				<b>CB2A</b>					
Direction	Flow control	Drainage Area	Lining Method	Joint Length	Year Laid	Year Renewed	Sewer Category		
<b>Downstream</b>	<b>Not Control...</b>						<b>SW</b>		

Video Name	Media Label	Additional Info	Purpose	Sheet
<b>CB2-CB2A_46676_11_05_2018.mpg</b>			<b>D</b>	<b>1</b>

Optional1	Optional2
Optional3	Optional4
Optional5	Optional6
Optional7	Optional8
Optional9	Optional10

Footage	Code	CD	Observation	At	To	V1	V2	%	Jt	Remarks	Img
<Start Inspection>											
0.0	AMH		Manhole							Starting manhole: CB2	X
0.0	MWL		Water Level					5			X
164.7	AMH		Manhole							Finishing manhole: CB2A	X
<Complete Inspection>											

