

# TV Inspection Report

## MH CB2A to CB5 Downstream Inspection

<b>PSR</b> CB2A-CB5		PO number	Status <b>Completed</b>	Date <b>11/05/2018</b>	Time <b>:13:33 AM</b>	Weather <b>Dry</b>		
Street <b>near E Ilex Dr and Lake Shore Dr</b>		City <b>Lake Shore</b>		Owner				
Customer	Surveyor Name <b>Marvin Vicente</b>	Cert # <b>U-0817-07008912</b>	Length Surveyed <b>134.7</b>	Total Length				
Location Code <b>Light Highway</b>	Location Details	Ht/Dia <b>24</b>	Width	Shape <b>Circular</b>	Material <b>RCP</b>	Pre-Cleaning <b>N</b>	Date Cleaned <b>11/05/2018</b>	Sewer Use <b>SW</b>
Upstream MH <b>CB2A</b>	US Rim to Inv	US Grd to Inv	US Rim to Grd	Downstream MH <b>CB5</b>	DS Rim to Inv	DS Grd to Inv	DS Rim to Grd	
Direction <b>Downstream</b>	Flow control <b>Not Control...</b>	Drainage Area	Lining Method	Joint Length	Year Laid	Year Renewed	Sewer Category <b>SW</b>	
Video Name <b>CB2A-CB5_46677_11_05_2018.mpg</b>		Media Label	Additional Info			Purpose <b>D</b>	Sheet <b>1</b>	

Optional1	Optional2
Optional3	Optional4
Optional5	Optional6
Optional7	Optional8
Optional9	Optional10

Footage	Code	CD	Observation	At	To	V1	V2	%	Jt	Remarks	Img
<b>&lt;Start Inspection&gt;</b>											
0.0	AMH		Manhole							Starting manhole: CB2A	X
0.0	MWL		Water Level					5			X
134.7	AMH		Manhole							Finishing manhole: CB5	X
<b>&lt;Complete Inspection&gt;</b>											

