

TV Inspection Report

MH MH5 to OF6 Downstream Inspection

PSR MH5-OF6	PO number	Status	Date	Time	Weather
		Survey Aba...	12/03/2018	:58:44 AM	

Street	City	Owner
Hawthorne Dr and LakeshorebDr	Lake Park	

Customer	Surveyor Name	Cert #	Length Surveyed	Total Length
	Marvin Vicente	U-0817-07008912	387.6	

Location Code	Location Details	Ht/Dia	Width	Shape	Material	Pre-Cleaning	Date Cleaned	Sewer Use
Light Highway		30		Circular	RCP	N	12/03/2018	SW
Upstream MH	US Rim to Inv	US Grd to Inv	US Rim to Grd	Downstream MH	DS Rim to Inv	DS Grd to Inv	DS Rim to Grd	
MH5				OF6				
Direction	Flow control	Drainage Area	Lining Method	Joint Length	Year Laid	Year Renewed	Sewer Category	
Downstream	Plugged						SS	

Video Name	Media Label	Additional Info	Purpose	Sheet
MH5-OF6_50753_12_03_2018.mpg			C	1

Optional1	Optional2
Optional3	Optional4
Optional5	Optional6
Optional7	Optional8
Optional9	Optional10

Footage	Code	CD	Observation	At	To	V1	V2	%	Jt	Remarks	Img
<Start Inspection>											
0.0	AMH		Manhole							Starting manhole: MH5	X
0.0	MWL		Water Level					5			X
387.6	MSA		Abandoned Survey							Inspection abandoned	X
<Complete Inspection>											