

Town of Jupiter Inlet Colony Major Outfalls Inventory

| Outfall ID | Outfall Location | Latitude | Longitude | Receiving Waters | Pipe Size | Pipe Material | Add'l Notes |
|-------------------|-------------------------|-----------------|------------------|-------------------------|------------------|----------------------|--|
| 1 | PBC ROW Swale | 26.95244 | -80.076908 | Indian River | 18" | RCP | |
| 2 | 103 Lighthouse Drive | 26.95048 | -80.078186 | | 24" | RCP | |
| 3 | 87 Lighthouse Drive | 26.94623 | -80.077452 | | 15" | VCP | |
| 4 | 75 Lighthouse Drive | 26.94556 | -80.073628 | Jupiter Inlet | 21" | PVC | 21" CMP pipe with existing dual 8" PVC through seawall |
| 5 | Beach Club Parking Lot | 26.9454 | -80.073157 | | 12" | RCP | |