

FLORIDA DEPARTMENT OF **Environmental Protection**

Ron DeSantis Governor

Jeanette Nuñez Lt. Governor

Noah Valenstein Secretary

Bob Martinez Center 2600 Blair Stone Road Tallahassee, FL 32399-2400

Phase I Municipal Separate Storm Sewer System (MS4) NPDES Stormwater Audit Report

Ι. **BACKGROUND INFORMATION**

MS4 Permit Name: Palm Beach County MS4 Permittee: City of Belle Glade **Permit Number:** FLS000018 (Cycle 3)

Annual Report Year: Year 6

Reporting Period: 09/2015 - 09/2016

Audit Date/Time: June 19, 2017 9:15 am – 12:00 pm

Inspector(s):

Name	Title	Phone/ Email
Michelle Bull	MS4 Coordinator	(850 245-7561
		Michelle.Bull@dep.state.fl.us

Permittee Representative(s):

Name	Title	Phone
Vince Akhimle	Public Services Director	561-996-0100
Johnny Gooden	Assistant Public Works	561-996-0100
	Director	JGooden@belleglade-fl.com
Karen Brandon	AECOM, Sr. Project Mgr.	561-684-3375
		Karen.Brandon@aecom.com
Lucinda Hood	Facility Manager	561-996-0100
Anne Capelli	Mock-Roos, Project Mgr.	561-683-3113
_		Anne.Capelli@mockroos.com

II. **GENERAL COMMENTS**

MS4 discharges to South Florida Conservancy District (agricultural canals) and to the Hillsborough Canal (SFWMD).

III.

SITE VISITS			
☐ Satisfactory	□ Unsatisfactory	☐ Not Applicable	

Site Type: Maintenance Yard

Site Name and Location: Belle Glade Municipal Complex, 110 Dr. Martin Luther King, Jr. Blvd.

Applicable Permit Provision(s): Part III.A.3

Observations: Storage of street sweeper, vac truck, mowing tractors, heavy equipment, garbage trucks (dump at Solid Waste facility daily) and four rear loaders. Bulk cold-patch is stored outside and uncovered on a concrete area. Indoor activities include oil changes and vehicle maintenance. There is a

wash area for washing motor parts with an oil/water separator that drains to sewage. The car wash rack is covered and bermed and drains to sewage. It is used to wash vehicles and rinse back of dump trucks daily. Reviewed monthly inspection report; had illicit discharge checkbox. No fueling station. Significant amounts of muck and debris were noted along the property-line ditch, and a culvert was impacted.

Due to the waste vehicle storage and maintenance, the facility may need coverage under the DEP Multi-Sector Generic Permit (MSGP), or industrial stormwater permit.

Images: Belle Glade Municipal Complex, June 19, 2017





Required Improvements:

- Within 30 days of the audit report, contact the NPDES Stormwater Notice Center to determine if MSGP coverage is needed for the Public Services Compound, specifically under Sector P Land Transportation, SIC Code 4212. Submit DEP's determination of need for MSGP coverage for this activity/facility.
- Sweep the yard regularly, clean trash around inlet and around the edges of property. May need to excavate swale and vac culvert on side of property. Within 30 days of the audit report, send images of the maintained yard and swale.

IV. SWMP IMPLEMENTATION REVIEW

Mor	nitoring Program				
X	Satisfactory	☐ Unsatisfactory		Not Applicable	
Sum	mary: Not reviewed during au	dit. Joint Monitoring program.			
Fisc	al Analysis				
Con	Comments: Not reviewed during audit.				
TM	DL Prioritization				
\boxtimes	Satisfactory	☐ Unsatisfactory		Not Applicable	
N/A					
Part III.A.1: Structural Controls and Stormwater Collection Systems Operation					
\boxtimes	Satisfactory	☐ Unsatisfactory		Not Applicable	
Major Outfall Inventory : Map reviewed shows watershed of major outfalls (6). Belle Glade Business park has a swale, dry detention, wet detention then a water control structure that discharges to					

Conservancy canal. Discussed the need to re-evaluate industrial area, may be considered a major based on

2 acres of industrial. See Section 62-624.200(9), F.A.C. Inventory may change in Year 1. The Business Park gets mowed weekly, and inspected at that time.

Discussed updating monthly major outfall report to refer to weekly report. Lu takes staff's weekly reports and fills out a summary of weekly activities, then does a monthly summary.

Structural Control Inventory: Discussed that treatment swales and conveyance swales reported are the same. Discussed reporting only as conveyance swales only. No ditches.

Structural Control Inspections: Lucinda. Submit weekly report, for weekly mowing. Building and Grounds-does mowing, checks pipes during mowing. Reviewed weekly/daily records which include storm drain cleaning. Reviewed before/after picture of cleaned storm drain.

Reviewed mowing/debris cleanup list and swale inspection checklist.

Catch Basins: inspected monthly – schedule maintenance based on inspections. Discussed the need to clean drains before settled debris reaches pipe height (some catch basin bottom may be at pipe level). Maintenance reported on weekly/daily report.

Part	Part III.A.2: Areas of New Development and Significant Redevelopment					
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable	
Not	reviewed during audit.					
Part	t III.A.3: Roadways					
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable	
Pick Up Events: Year 1: Stop the Violence, Clean the City (NFL project). PB Sherriff Office and Christ Fellowship, Great American Cleanup, local sorority. PB Sherriff Office on 2/27/2017. Hauling ticket may have included more than clean up. Clean up usually picks up bulk items needing equipment. Also used as an amnesty day. Street Sweeping: One City-owned sweeper, one driver, works 4 days a week. Reviewed sweeper report. Keeps mileage when starts and stops sweeping. Discussed using a trip meter to get more accurate sweeping mileage. Reviewed sweeping reports. Sweeps most roads daily, sweeps some weekly. Picks up more litter than sand. Dumps truck at Solid Waste Authority transfer station daily. Road Maintenance Yards: See Section III of this report, above.						
Part	t III.A.4: Flood Control Proje	ects				
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable	
Not	reviewed during audit.					
Part III.A.5: Municipal Waste Treatment, Storage, and Disposal Facilities Not Covered by an NPDES Stormwater Permit						
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable	
	Waste Storage Facilities : N/A. All trash and debris taken to private transfer station daily. See Part III.A.3					

Part	III.A.6: Pesticides, Herbicide	s, a	nd Fertilizer Application		
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable
Not	reviewed during audit.				
	III.A.7.a: Illicit Discharges a ections, Ordinances, and Enfo		• • •		
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable
Not	reviewed during audit.				
	III.A.7.c: Illicit Discharges a stigation of Suspected Illicit I		mproper Disposal — harges and/or Improper Dispo	sal	
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable
Proactive Inspections: tracked with mowing/structural inspections. 52 inspections were weekly mowing inspection. Reactive Inspections: Code Enforcement. Enforcement: Report to Code Enforcement. Training: previously trained mowing staff on Excal ID video. Part III.A.7.d: Illicit Discharges and Improper Disposal—					
	Prevention and Response				
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable
Not	reviewed during audit.				
	III.A.7.e: Illicit Discharges a	nd I	mproper Disposal —		
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable
Public Education : Marquee at City Hall for ID calls. Mock-Roos: PSAs on TV on Comcast, covers entire County, Exfinity website, directs to Stormwater and Me website and MS4 contact list. No PIO on staff, makes it hard to do education. Suggest contacting Mock-Roos to do door hangers to reach non-Comcast residents. Discuss doing one in Spanish. Also discussed updating Code Enforcement hangers to include ID topics.					
	III.A.7.f: Illicit Discharges an Toxics, and Household Haza		• •		
\boxtimes	Satisfactory		Unsatisfactory		Not Applicable
prob resid	lem with large items being dum	ped , lot	evides trash and bulk pick up to a into canals. City staff require v of transient, non-English speak e education.	iola	tors to pick up if caught. Many

	t III.A.7.g: Illicit Disch itation of Sanitary Sev	arges and Improper Disposal — ver Seepage					
\boxtimes	Satisfactory	☐ Unsatisfactory	☐ Not Applicable				
Spil	ls: County took over o	peration of WWTP and sanitary col	lection system.				
		and High-Risk Runoff— and Procedures for Inspections					
\boxtimes	Satisfactory	☐ Unsatisfactory	☐ Not Applicable				
High disc	Not reviewed during audit. High risk facilities : Mostly handled by Code Enforcement. AMEC reviewed TRI list. Most don't discharge into MS4. Inspections : 2 by Code Enforcements. Reported to AMEC via email.						
	t III.A.8.b: Industrial a nitoring for High Risk	and High-Risk Runoff— Industries					
\boxtimes	Satisfactory	☐ Unsatisfactory	☐ Not Applicable				
Mor	nitoring: N/A						
	t III.A.9.a: Construction Planning and Non-Str	on Site Runoff— ructural and Structural Best Man	agement Practices				
\boxtimes	Satisfactory	☐ Unsatisfactory	☐ Not Applicable				
	Site Plan Review: First Bank project was less than .25 acres. ERP/CGP Coverage: N/A						
Part III.A.9.b: Construction Site Runoff— Inspection and Enforcement							
\boxtimes	Satisfactory	☐ Unsatisfactory	☐ Not Applicable				
Insp	Inspections: Done by Code Enforcement. None required in Year 6.						
Part III.A.9.c: Construction Site Runoff— Site Operator Training							
	Satisfactory	□ Unsatisfactory	☐ Not Applicable				
annı	Inspector E&SC Training: Ralph Butts (Code Compliance) has Inspector Training in 2012. Needs annual refresher training. Site Plan Reviewer Training: Planning Group does site plan reviews. Craig Smith does site plan review.						
_							

Required Improvements: In future reporting periods, provide refresher training for inspector and site plan reviewer. Discussed checking out Excal video from Mock-Roos.