SECTION VII.	STORMWATER MANAGEMENT PROGRAM (SWMP) SUMMARY TABLE								
A.	B.	C.	D.	E.	F.				
Permit Citation/ SWMP Element	Permit Requirement/Quantifiable SWMP Activity	Number of Activities Performed	Documentation / Record	Entity Performing the Activity	Comments				
	CONTRACTORS: FDACS certified / licensed applicators of fertilizer	1	License	Grassroots, Inc.					
	Provide a copy of the adopted ordinance with the Year 2 Annual Report. If this provision is not applicable because the permittee is not within the watershed of a nutrient-impaired water body, indicate that in Column F.								
	Year 2 ONLY: Attach copy of adopted Florida-friendly ordinance								
	Report on the public education and outreach activities that are performed or sponsored by the permittee within the permittee's jurisdiction to encourage citizens to reduce their use of pesticides, herbicides and fertilizers including the type and number of activities conducted, the type and number of materials distributed, and the number of Web site visits (if applicable).								
	Public Education and Outreach Program The public outreach and education plan is carried out as a joint effort								
		the Palm Beach C							
		County Joint Annual Report for the public education and outreach information.							
	Provide an evaluation of the Stormwater Management Program according to Part VI.B.2	2 of the permit.							
Part III.A.6	Strengths: Guideline Documentation								
Summary	Limitations: None								
	SWMP revisions implemented to address limitations: None, Northern employees of	lo not apply Herbicio	des, Pesticides or Fe	ertilizers					
Part III.A.7.a	Illicit Discharges and Improper Disposal — Inspections, Ordinances, and Enforce	ment Measures							
	Report amendments in Year 4.								
	Year 4 ONLY: Attach a report on amendments to applicable legal authority								
Part III.A.7.c	Illicit Discharges and Improper Disposal — Investigation of Suspected Illicit Discharges and/or Improper Disposal								
	Report on the proactive inspection program, including the number of inspections conducted by the permittee, the number of illicit activities found, and the number and type of enforcement actions taken.								
	Proactive inspections for suspected illicit discharges	34,541	N/A	N/A	None suspected				
	Illicit discharges found during a proactive inspection	0	N/A	N/A	None found				
	NOV/WL/citation/fines issued for illicit discharges found during proactive inspection	0	N/A	N/A	None issued				
	Report on the reactive investigation program as it relates to responding to reports of suspected illicit discharges, including the number of reports received, the number of investigations conducted, the number of illicit activities found, and the number and type of enforcement actions taken.								
	Reports of suspected illicit discharges received	0	N/A	N/A	None				
	Reactive investigations of reports of suspected illicit discharges etc.	0	N/A	N/A	None				
	Illicit discharges etc. found during reactive investigation	0	N/A	N/A	None				
	NOV/WL/citation/fines issued for illicit discharges etc. found during reactive investigation	0	N/A	N/A	None				
	Report the type of training activities, and the number of permittee personnel and contractors trained (both in-house and outside training) within the reporting year.								
	Personnel trained	11	Sign – in sheet	NPBCID	Video training				
	Contractors trained	7	Sign – in sheet	NPBCID	Video training				

SECTION VII.	STORMWATER MANAGEMENT PROGRAM (SWMP) SUMMA	ARY TABLE							
A.	B.				C.		D.	E.	F.
Permit Citation/ SWMP Element	Permit Requirement/Quantifiable SWMP Activity				Number of Activities Performed		Documentation / Record	Entity Performing the Activity	Comments
							3.) Annual Facilities Inspection Report (61)	Facilities Inspection Report - J. Iles	
	Lake Interconnects / pipes / culverts (LF)	104,354	9 Days	4.6	6 Days	3.75	Inspection reports	1.) Thompson Contracting. – J. Iles 2.) EMC Divers Inc. – J. Iles	
	Roadway Drainage Pipes (LF)	76,868	0	0	0	0	Daily work reports Inspection reports	1.) – J. Santos	2 nd 5 year entire system cleaning program started 10/2017
	Inlets / catch basins / grates	924	26 (trips) x # C.B (924)	100	0	0	Catch basin/ Inlet Inspection (474)	NPBCID-J. Santo	No maintenance required this reporting period
	Ditches / Canals (miles)	48.92	<u>24,024</u> <u>459</u>	100	176	100	Schedule of Values & Work Completed. (24) 2.) NPBCID Canal R.O.W. Inspection Form. (283) 3.) Treatment Performed in Lakes and Canal (140)	1.)Grassroots, Inc J. Iles 2.) NPBCID Staff - R Cross 3.) Clark Aquatics/Future Horizons -R Cross	
							4.) Grassroots, Inc. contract (12)	4.) Grassroots, Inc R Cross	
	If the minimum inspection frequencies set forth in Table II.A.1.a. were not met, provide as an attachment an explanation of why they were not and a description of the actions that will be taken to ensure that they will be met.					N/A	N/A	Met requirements	

- Projects Completed (1)
 - (Unit 11) Cypress Pointe Drainage Repair

Part III.A.9.a (Construction Site Runoff Site Planning)

Construction Site Plan/Permit Application Reviews (Private Site) (25)

See attached completed Site Plan Review forms

Construction Site Plan Reviews (District Site) (3)

- (Unit 5A) Vista Center Sidewalk Plans Phase 3
- (Unit 11) Cypress Pointe Drainage Repair
- (Unit 11) Coventry Curbing Plans

Part III.A.9.b (Construction Site Runoff Inspection and Enforcement)

Construction Site Inspections Conducted (Private Sites) (37)

- PER-2C-004 UTC Center for Intelligent Buildings 4
- PER-2C-005 Atlantico at Palm Beach Gardens
- PER-2C-006 Alton Club
- PER-2C-007 Clarity Pointe 4
- PER-5A-073 Emerald Dunes Golf Course
- PER-07-059 Cheney Brothers Berm and Parking in Canal ROW
- PER-9B-052 Windsor Park West- Phases 2A & 2B
- PER-16-119 Palm Beach Park of Commerce Camera Installation
- PER-16-128 Project Beach Ball
- PER-19-080 La Posada ALF and Wellness Center Building Construction
- PER-47-004 Loxahatchee Reserve 5 CFS Pump Station
 1- admin inspection for bill of sale only

Northern Palm Beach County Improvement District

Construction Site Inspection Form

Site:	WF0590.1	N0057	PER-2C-004 UTC Center for Intelligent Buildings Date of Inspection: 10-3-	16
Addr	ess: <u>Unit</u>	2C wes	of Pasteur Blvd. at Donald Ross Road	
Rece	iving wate	r body	Unit 2C Master System	
Outf	all Locatio	n/ ID N	mber: <u>WMT-W Per PB 120 Pgs 187 & 188</u>	
Inspe	ectors Nan	ne: <u>: Ki</u>	Leser NPBCID Permit Number: PER-2C-004	
Proje	ect owner:	\boxtimes	rivate Northern Palm Beach County Improvement District	
YES	NO	N/A		
	\boxtimes		Erosion & Sedimentation Controls are installed as shown on plan.	
	\boxtimes		Erosion is being controlled on site.	
	\boxtimes		Sedimentation is being contained on site.	
\boxtimes			No indication of sedimentation leaving the site.	
		\boxtimes	SWPP & completed inspection forms are on site & available.	
		\boxtimes	NOI on site	
		\boxtimes	Prior non-compliance issues have been addressed.	
\boxtimes			All other sources of pollution are being controlled.	
	\boxtimes		Illicit discharges or illicit connections detected.	

Comments:

It does not appear that the silt fence or any kind of filter fabric or any other BMP's are being maintained. Rock Bed at Construction Exit full of dirt needs to be repaired with fresh rock. Contractor has floating silt barrier in lake where work is being done.