



Storm Drain Maintenance Form

Date: 10/18/18

Work Order No. _____

Address or nearest intersection: Municipal Services Wash Rack

Number of catch basins cleaned: 4

Estimated amount of debris removed: 4 c/y




Length of pipe that was jetted out: 23'

Illicit Connections found? Yes _____ No X

Problems reported to supervisor: _____

Comments: _____

Sketch:





Storm Drain Maintenance Form

Date: 11/5/18

Work Order No. _____

Address or nearest intersection: Municipal Services Wash Rack

Number of catch basins cleaned: 4

Estimated amount of debris removed: 12 c/y



Length of pipe that was jetted out: 23'

Illicit Connections found? Yes _____ No X

Problems reported to supervisor: _____

Comments: _____

Sketch: Wash Rack





Storm Drain Maintenance Form

Date: 11/15/18

Work Order No. _____

Address or nearest intersection: Municipal Services - Wash Rack

Number of catch basins cleaned: 4

Estimated amount of debris removed: 4 9/16



Length of pipe that was jetted out: 23'

Illicit Connections found? Yes _____ No X

Problems reported to supervisor: _____

Comments: _____

Sketch:
Wash Rack





Storm Drain Maintenance Form

Date: 11/23/18

Work Order No. _____

Address or nearest intersection: 2500 NW 1ST AVE
WASH RACK

Number of catch basins cleaned: 4

Estimated amount of debris removed: 12 cyd


Length of pipe that was jetted out: 23 Ft

Illicit Connections found? Yes _____ No

Problems reported to supervisor: _____

Comments: _____

Sketch:





Storm Drain Maintenance Form

Date: 2/21/18

Work Order No. _____

Address or nearest intersection: Municipal Services Wash Rack

Number of catch basins cleaned: 4

Estimated amount of debris removed: 8 c/y



Length of pipe that was jetted out: 23'


Illicit Connections found? Yes _____ No X

Problems reported to supervisor: _____

Comments: _____

Sketch: Wash Rack





Storm Drain Maintenance Form

Date: 1/2/19

Work Order No. _____

Address or nearest intersection: 2500 NW 15TH AVE

(WASH RACK)

Number of catch basins cleaned: 4

Estimated amount of debris removed: 12 CYDS


Length of pipe that was jetted out: 23 FT

Illicit Connections found? Yes _____ No

Problems reported to supervisor: _____

Comments: _____

Sketch:





Storm Drain Maintenance Form

Date: 1/8/19

Work Order No. _____

Address or nearest intersection: Municipal Services Wash Rack

Number of catch basins cleaned: 4

Estimated amount of debris removed: 8 c/y


Length of pipe that was jetted out: 23'

Illicit Connections found? Yes _____ No X

Problems reported to supervisor: _____

Comments: _____

Sketch:





Storm Drain Maintenance Form

Date: 1/29/19

Work Order No. _____

Address or nearest intersection: Municipal Services Wash Rack

Number of catch basins cleaned: 4

Estimated amount of debris removed: 8 9/4


Length of pipe that was jetted out: 23'

Illicit Connections found? Yes No

Problems reported to supervisor: _____

Comments: _____

Sketch:





Storm Drain Maintenance form

Date: 2/19/19

Work Order No. _____

Address or nearest intersection: Municipal Services Wash Rack

Number of catch basins cleaned: 4

Estimated amount of debris removed: 8 1/4



Length of pipe that was jetted out: 23'

Illicit Connections found? Yes _____ No X


Problems reported to supervisor: _____

Comments: Excercise shut off valve

Sketch:



2078



Storm Drain Maintenance Form

Date: 9/18/19

Work Order No. _____

Address or nearest intersection: Wash. Rack Municipal Services

Number of catch basins cleaned: 4

Estimated amount of debris removed: 6 c/y.


Length of pipe that was jetted out: 23'

Illicit Connections found? Yes _____ No X

Problems reported to supervisor: _____

Comments: _____

Sketch:



City of Boca Raton
Municipal Services Department
Streets Division
Work Order

Work Order Number: _____
Requesting Department: Stormwater
Requestor: P. Baker
Address: Municipal Services - Wash Rack
Job Information: Clean Wash Rack
Start Date: 4/29/19

LABOR			EQUIPMENT		MATERIALS	
Date	Employees	Hours	Number	Hours	Item	Qty
4/29/19	C. Range	2.5	8518	2.5		
4/29/19	L. Jackson	2.5	8518	2.5		

COMMENTS:

