

TV Inspection Report

MH CB132 to CB133

Downstream Inspection

PSR CB132-CB133	PO number	Status Completed	Date 11/05/2018	Time 30:33 PM	Weather Dry
---------------------------	-----------	----------------------------	---------------------------	-------------------------	-----------------------

Street corner of Date Palm Dr and Lake Shore Dr	City Lake Shore	Owner
---	---------------------------	-------

Customer	Surveyor Name Marvin Vicente	Cert # U-0817-07008912	Length Surveyed 50.7	Total Length
----------	--	----------------------------------	--------------------------------	--------------

Location Code Light Highway	Location Details	Ht/Dia 15	Width	Shape Circular	Material RCP	Pre-Cleaning J	Date Cleaned 11/05/2018	Sewer Use SW
---------------------------------------	------------------	---------------------	-------	--------------------------	------------------------	--------------------------	-----------------------------------	------------------------

Upstream MH CB132	US Rim to Inv	US Grd to Inv	US Rim to Grd	Downstream MH CB133	DS Rim to Inv	DS Grd to Inv	DS Rim to Grd
-----------------------------	---------------	---------------	---------------	-------------------------------	---------------	---------------	---------------

Direction Downstream	Flow control Not Control...	Drainage Area	Lining Method	Joint Length	Year Laid	Year Renewed	Sewer Category SW
--------------------------------	---------------------------------------	---------------	---------------	--------------	-----------	--------------	-----------------------------

Video Name CB132-CB133_46682_11_05_2018.mpg	Media Label	Additional Info	Purpose D	Sheet 1
---	-------------	-----------------	---------------------	-------------------

Optional1	Optional2
Optional3	Optional4
Optional5	Optional6
Optional7	Optional8
Optional9	Optional10

Footage	Code	CD	Observation	At	To	V1	V2	%	Jt	Remarks	Img
<Start Inspection>											
0.0	AMH		Manhole							Starting manhole: CB132	X
0.0	MWL		Water Level					5			X
10.0	IW		Infil Weeper	12							X
10.0	MGP		General Photo								X
50.7	AMH		Manhole							Finishing manhole: CB133	X
<Complete Inspection>											

