

TV Inspection Report

MH CB2 to CB1 Upstream Inspection

PSR CB1-CB2	PO number	Status Completed	Date 11/05/2018	Time 18:37 PM	Weather Dry
------------------------------	-----------	----------------------------	---------------------------	-------------------------	-----------------------

Street near 600 Blk of Lake Shore Dr	City Lake Shore	Owner
--	---------------------------	-------

Customer	Surveyor Name Marvin Vicente	Cert # U-0817-07008912	Length Surveyed 34.6	Total Length
----------	--	----------------------------------	--------------------------------	--------------

Location Code Light Highway	Location Details	Ht/Dia 18	Width	Shape Circular	Material RCP	Pre-Cleaning J	Date Cleaned 11/05/2018	Sewer Use SW
---------------------------------------	------------------	---------------------	-------	--------------------------	------------------------	--------------------------	-----------------------------------	------------------------

Upstream MH CB1	US Rim to Inv	US Grd to Inv	US Rim to Grd	Downstream MH CB2	DS Rim to Inv	DS Grd to Inv	DS Rim to Grd
---------------------------	---------------	---------------	---------------	-----------------------------	---------------	---------------	---------------

Direction Upstream	Flow control Not Control...	Drainage Area	Lining Method	Joint Length	Year Laid	Year Renewed	Sewer Category SW
------------------------------	---------------------------------------	---------------	---------------	--------------	-----------	--------------	-----------------------------

Video Name CB1-CB2_46679_11_05_2018.mpg	Media Label	Additional Info	Purpose D	Sheet 1
---	-------------	-----------------	---------------------	-------------------

Optional1	Optional2
Optional3	Optional4
Optional5	Optional6
Optional7	Optional8
Optional9	Optional10

Footage	Code	CD	Observation	At	To	V1	V2	%	Jt	Remarks	Img
<Start Inspection>											
0.0	AMH		Manhole							Starting manhole: CB2	X
0.0	MWL		Water Level					5			X
34.6	AMH		Manhole							Finishing manhole: CB1	X
<Complete Inspection>											