

TV Inspection Report

MH CB4 to CB3 Upstream Inspection

PSR CB3-CB4	PO number	Status	Date	Time	Weather
		Completed	11/05/2018	:24:03 AM	Dry

Street	City	Owner
corner of Hawthorne Dr and Lake Shore Dr	Lake Park	

Customer	Surveyor Name	Cert #	Length Surveyed	Total Length
	Marvin Vicente	U-0817-07008912	50.0	

Location Code	Location Details	Ht/Dia	Width	Shape	Material	Pre-Cleaning	Date Cleaned	Sewer Use
Light Highway		15		Circular	RCP	J	11/05/2018	SW

Upstream MH	US Rim to Inv	US Grd to Inv	US Rim to Grd	Downstream MH	DS Rim to Inv	DS Grd to Inv	DS Rim to Grd
CB3				CB4			

Direction	Flow control	Drainage Area	Lining Method	Joint Length	Year Laid	Year Renewed	Sewer Category
Upstream	Not Control...						SW

Video Name	Media Label	Additional Info	Purpose	Sheet
CB3-CB4_46674_11_05_2018.mpg			D	1

Optional1	Optional2
Optional3	Optional4
Optional5	Optional6
Optional7	Optional8
Optional9	Optional10

Footage	Code	CD	Observation	At	To	V1	V2	%	Jt	Remarks	Img
<Start Inspection>											
0.0	AMH		Manhole							Starting manhole: CB4	X
0.0	MWL		Water Level					5			X
50.0	AMH		Manhole							Finishing manhole: CB3	X
<Complete Inspection>											

