## **Town of Lake Park**

## MUNICIPAL MAINTENANCE YARD INSPECTION CHECKLIST

(NPDES Stormwater Inspection Checklist)

DATE/TIME:	June 5, 2019	/ 2:05	<b>p.m.</b>	
SITE NAME AN	ND LOCATION:	DPW Sanitation & Fa	cilities Maint.	Yard @ 650 Old Dixie Hwy.
DESCRIPTION OF ACTIVITIES: RECEIVING WATER BODY:		Sanitation Fleet Storage & Maint.; Fleet Fueling & Washing		
		Town of Lake Park MS4 & PBC Roads & Streets/Stormwater System		
FUELING AREA  X Check operati X Check Dispen X Inspect Fuel To X Check Fuel To X Check Exterion X Dry Clean-up  VEHICLE AND I X Proper Storag	on of Emergency Fuel Shurser Nozzles and Hoses for Tanks for conditions as per anks for Proper Decals and or of Fuel Tanks for rust or ic Leak Detection System for Supplies available for Fuel EQUIPMENT MAINT e & Disposal of Grease Rage & Disposal of Spent Cooe & Disposal of Batteries.	t-off Switch. leaks. PBC DERM. Placards. corrosion. or Fuel Tanks. I Spills. ENANCE gs.		Comments:  Replaced faded placards for gasoline tank.
X Inventory of n X Liquid waste	aterials stored properly with materials maintained onsite disposed of properly and no ans are cleaned and stored p	with labels & Material Sa ot being poured into storm		
OUTDOOR VEHICLE AND EQUIPMENT STORAGE  X Dip Pans used during maintenance of vehicles.  X Dip Pans cleaned and stored properly.  X Storage Area covered and maintained properly.  X Ground free of visual stains from oil or other vehicle fluids.  X Hazardous Materials stored properly without evidence of spills.				
<ul> <li>VEHICLE AND EQUIPMENT WASHING AREA</li> <li>X Area designated for cleaning activities.</li> <li>X Parts and equipment washed within proper cleaning area.</li> <li>X Employees trained on proper washing procedures.</li> <li>X Hazardous Materials stored properly without evidence of spills.</li> </ul>				
X Safeguards ins X System inspec X Employees tra X Storage Conta	GE IN ABOVEGROUN stalled, such as, Secondary eted weekly. hined on proper filling and a hiners maintained in good c indication of illicit discharge	Containment. transfer procedures. ondition.		
Inspection perform	ed by: Henry Rossario  Mechanic II			_(Signature) (Title)